	4	3			2		1	
				ZONE SHEET1	REV. REVO	DESCRIPT INITIAL REL	DATE A	APPROVED Witte S.
В		Ø 1.000						
A	CONDITIONS CONDITIONS PART IS TO BE FREE OF SCRATCHES, DENTS, AND DEFECTS CAUSED DURING PRODUCTION. PART IS TO BE FREE OF GREASE, AND DISCOLORATION ON ALL SURFACES. PARTS MUST BE PACKAGED IN A MANOR SUITABLE TO AVOID DAMAGE DURING TRANSPORT, STORAGE, AND HANDLING	MAGNETIZED: AXIAL Br (KG): 12.8-13.2 HcB (KOe): ≥11.5 Hci (KOe): ≥12.0 BHmax (MGOe): 40-43 MAXIMUM TEMPERATURE: 80C / 176F	PROPRIETARY AND CONFIDENTIAL THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF AMAZING MAGNETS LLC ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF AMAZING MAGNETS LLC IS PROHIBITED. CAGE CODE 4R1R7	DIMENSIONS / TOLERANCES: ANGULAR: M. TWO PLACE D THREE PLACE	ACH ± 1° DECIMAL ± 0.005" DECIMAL ± 0.004" CALE DRAWING	DRAWNPearson C.6/1CHECKEDWitte S.6/1	B/ CONTRIE	REV 0
	4	3			2		1	



В

Α