A Intervention of the second procession of th		4	3		2			1	
A Interference and an order of the first of							REVISIONS		
					ZONE REV.	DESCRIPTI	ON	DATE	APPROVED
					SHEET1 REVO	INITIAL RELI	ASE	3/5/2020	Spencer W.
A CONTROL AND ADDRESS AND DEFECTS PARTIS TO BE FREE OF SCRATCHES, DENTS, AND DEFECTS CALLSE DO VERME APPOLICION PARTIS TO BE FREE OF SCRATCHES, DENTS, AND DEFECTS CALLSE DO VERME APPOLICION PARTIS TO BE FREE OF SCRATCHES, DENTS, AND DEFECTS CALLSE DO VERME APPOLICION PARTIS TO BE FREE OF SCRATCHES, DENTS, AND DEFECTS PARTIS TO BEFREE OF SCRATCHES, DENTS, AND DEFECTS PARTIS TO PERES PARTIS TO BEFREE OF SCRATCHES, DENTS, DENTS, DENT	В		.187						
2. PARTS NO BE PREE OF GREASE, AND DISCOLORATION ON ALL SURFACES. Comments in contained in the promotion contenergy in the contained in the promotion contained in	A		0.250						
2. PARTS NO BE FREE OF GREASE, AND DISCOLORATION ON ALL SURFACES. COMMENSION OF ARLINING CONTAINED IN THIS SURFACES. Dimension contained in the Surfaces.									NG
SURFACES. 3. PARTS MUST BE PACKAGED IN A MANOR SUITABLE TO AVOID DAMAGE DURING TRANSPORT, STORAGE, AND HANDLING HC (KOe): ≥10.0 Hci (KOe): >11.0 BHmax (MGOe): 50-53 MAXIMUM TEMPERATURE: 70C / 158F HC B (LO C) = 10.0 HC (KOe): >10.0 HC (KOE) (		CAUSED DURING PRODUCTION.	GRADE: N52				12020 <b>(</b>	// MAGNE	TS°
Hci (KOe): ≥11.0 BHmax (MGOe): 50-53 MAXIMUM TEMPERATURE: 70C / 158F CAGE CODE 4R1R7		SURFACES. 3. PARTS MUST BE PACKAGED IN A MANOR SUITABLE TO AVOID	MAGNETIZED: AXIAL Br (KG): 14.3-14.8 HCB (KOel: ≥10.0	DRAWING IS THE SOLE PROPERTY OF MAZING MAGNETS LLC ANY 'EPRODUCTION IN PART OR AS A WHOLE VITHOUT THE WRITTEN PERMISSION OF	TOLERANCES: ANGULAR: MACH ± 1° TWO PLACE DECIMAL ± 0.005"	CHECKED Spencer W. 3/5		R250A2-N5	52
MAXIMUM TEMPERATURE: 70C / 158F CAGE CODE <b>B</b> R250A2-N52-SPECS			Hci (KOe): ≥11.0 BHmax (MGOe): 50-53	ROHIBITED.		COMMENIS:			REV
DO NOT SCALE DRAWING			MAXIMUM TEMPERATURE: 70C / 158F				Ď	KZJUAZ-INJZ-JYEC	CS <b>O</b>
					DO NOT SCALE DRAWING				
4 3 1		4	3		2			1	

